

## VEHICLE INSPECTION REPORT

**LG70EVM**

### Citroen Relay 35 2.2 BLUE HDI 140PS

**Non Runner**  
Inspection

<b>Serious Damage?</b>	No	<b>Vehicle</b>	
		<b>VAT</b>	Plus VAT
		<b>V5</b>	Buyer To Apply

#### Details

<b>Reg. date</b>	15/09/2020	<b>Colour</b>	BLACK	<b>CAP Average</b>	£8,250.00
<b>Year</b>	2020	<b>VIN</b>	VF7YDBNFC12P34471	<b>CAP Below</b>	£6,775.00
<b>Mileage</b>	61,758 Miles Not Warranted	<b>Body Style</b>	Panel Van L4	<b>Gearbox</b>	MANUAL
<b>Fuel Type</b>	Diesel	<b>CAP Clean</b>	£9,250.00	<b>Gears</b>	6

\*NON RUNNER, CRANKS BUT WILL NOT FIRE\* SIDE LOADING DOOR, TOW BAR, E/MIRRORS

#### Tyres

NSF

NSR

OSF

OSR


Spare

## Features

- Navigation system
- Rear parking sensor
- Air conditioning
- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Wing Front Arch Extension os  
Scuffed (Unpainted)  
UpTo 100mm



2: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm



3: Other  
N/A  
N/A



4: Bonnet  
Scratched  
UpTo 25mm Thru Paint



5: Door nsr  
Chipped  
Multiple Chips



6: Sill ns  
Chipped  
Multiple Chips



7: Qtr Panel nsr  
Scratched  
UpTo 25mm Thru Paint



8: Panel Rear  
Dented  
Between 10mm + 30mm





9: Door nsr  
Scratched  
UpTo 25mm Thru Paint



10: Badgedecal Rear  
Broken  
Replace



11: Door osr  
Chipped  
Edge Chip



12: Bumper Rear Moulding  
Scuffed (Unpainted)  
UpTo 100mm



13: Door osf  
Scratched  
Over 25mm Thru Paint



14: Door Mirror Assy osf  
Scuffed (Unpainted)  
UpTo 100mm



15: Flasher Side Repeater os  
Broken  
Replace



16: A Post os  
Scratched  
UpTo 25mm Thru Paint



17: Other  
N/A  
N/A



18: Sill os  
Rusted  
Over 5mm

**Interior**

**Carpet Condition**      Average  
**Seat Condition**      Average

**Engine Runs**      Fault

**Upholstery Condition**      Average  
**Odour**      No