

VEHICLE INSPECTION REPORT

PN19DLK

Fiat Ducato 35 2.3 MULTIJET 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 14/08/2019

Year 2019

Mileage 101,781 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA25000002K87400

Body Style Dropside

MOT Due Expired

CAP Clean £4,625.00

CAP Average £4,050.00

CAP Below £3,225.00

Gearbox MANUAL

Gears 6

Tail Lift Column

LARGE CRACK IN WINDSCREEN E/ MIRRORS, TOW BAR

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Park assist camera
- Front electric windows
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
Over 25mm



3: Wing nsf
Dented
With Paint Damage



4: B Post ns
Dented
Over 30mm



5: B Post os
Dented
Over 30mm



6: Door osf
Dented
With Paint Damage




7: Screen Front
Cracked
Replace



8: Door Pad osf
Soiled
Heavy



9: Carpets Front
Holed
Over 3mm



10: Seat Base Cover osf
Torn
Over 3mm



11: Seat Base Cover nsf
Soiled
Heavy



12: Door Pad nsf
Soiled
Heavy

Interior

Carpet Condition	Poor		Upholstery Condition	Poor
Seat Condition	Poor		Odour	No
Engine Runs	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			