

VEHICLE INSPECTION REPORT



Isuzu N75 190

Inspection	Vehicle	
Serious Damage? No	VAT	Plus VAT
	V5	Present

Details

Reg. date	12/03/2019	Colour	BLUE/YELLOW	Cab Type	DAY CAB
Year	2019	VIN	JAANPR75MJ7100308	Gearbox	AUTOMATIC
Mileage	282,177 Km Warranted	Body Style	Dropside	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/09/2025	Rear Suspension	Steel

WARNING LIGHT ON DASH FULL WIDTH RAMP, HYDRAULIC RAMPS, SURROUND CAMERA SYSTEM, BEEN ON FULL R&M CONTRACT FORM NEW

Tyres					
NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OSO3	OSO4	

Features

Park assist camera
Passenger airbag
Cloth seat trim
Front electric windows
Orivers airbag

Photos




































Condition Check



Damage Photos



1: Door osf Dented Over 30mm 2: Door osf Dented Over 30mm





3: Door osf Dented Over 30mm



5: Bumper Front Scratched Over 100mm Thru Paint



6: Headlamp os Broken Replace



7: Bonnet Dented Over 30mm



8: Bonnet Dented Over 30mm





9: Bumper Front Scratched Over 100mm Thru Paint

10: Door nsf Dented With Paint Damage



11: Dash Warning Lights Displayed No Action

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average -	
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		Fault	DPF light illuminated		Fault
ABS light illuminated		OK			