

# **VEHICLE INSPECTION REPORT**

YD67VHH

## Daf LF 260 18 TONNE

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present	-	
Details					
Reg. date	13/09/2017	VIN	XLRAEL3700L466758	Axle Combi	4x2
Year	2017	Body Style	Flatbed	Steering Combi	Steer
Mileage	312,555 Km Warranted	Keys	2	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Column
Colour	WHITE	Gearbox	Automatic	-	

### Gas Bottle Carrier Body

#### **Tyres**

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OSO3	OSO4	

### **Features**

- Bluetooth connectionDrivers airbag
- Cruise control
   Cloth seat trim
- Radio/CD

Air conditioning

#### **Photos**
















# **Condition Check**



# **Damage Photos**



1: Carpets Front Torn Over 10mm



2: Seat Base Cover osf Torn Over 3mm



3: Door Moulding osf Scuffed (Unpainted) Over 100mm



4: Bonnet Chipped 1 To 5



5: Bumper Front Grill Broken Replace



6: Bumper Front Scratched UpTo 25mm Not Thru Paint



7: Wing osf Scratched UpTo 25mm Thru Paint



8: Door osf Dented Over 30mm



9: Qtr Panel osr Rusted Over 5mm



10: Tailgate Rusted Over 5mm



11: Qtr Panel nsr Rusted Over 5mm



12: Wing nsf Scratched UpTo 25mm Thru Paint

### Interior

Carpet Condition Seat Condition	Poor Poor		Upholstery Condition Average Odour -	
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake		OK	No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK

WindowsOKRadioOKSteeringOK