

VEHICLE INSPECTION REPORT

PE63NPP

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 20/11/2013

VIN XLRAE45FF0L432871

Gearbox MANUAL

Year 2013

Body Style Box Van

Rear Suspension Steel

Mileage 822,597 Km Warranted

Service history Yes

Tail Lift Cantilever

Fuel Type Diesel

MOT Due 31/05/2026

Colour RED

Cab Type DAY CAB

COLLECTED AS NON RUNNER, CORROSION

Tyres

NSF NSI1 NSI2 NSI3 NSI4


OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Screen Front
Chipped
UpTo 10mm



5: Bumper Front
Dented
With Paint Damage



6: Wing nsf
Cracked
Replace



7: Bumper Front
Scratched
25 to 100mm Thru Paint



8: Other
N/A
N/A



9: Bumper Rear
Rusted
Over 5mm



10: Other
N/A
N/A



11: Seat Back Cover osf
Scuffed
Over 25mm



12: Other
N/A
N/A



13: Other
N/A
N/A



14: Seat Base Cover nsf
Torn
Over 3mm



15: Other
N/A
N/A

16: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	