

# **VEHICLE INSPECTION REPORT**



## Nissan Cabstar 35.14 DCI

| Inspection         | Vehicle |          |  |
|--------------------|---------|----------|--|
| Serious Damage? No | VAT     | Plus VAT |  |
|                    | V5      | Present  |  |

#### Details

| Reg. date | 29/04/2013                | VIN              | VWADPTF24D3154472 | Gearbox         | MANUAL |
|-----------|---------------------------|------------------|-------------------|-----------------|--------|
| Year      | 2013                      | Body Style       | Tipper            | Gears           | 6      |
| Mileage   | 37,879 Miles<br>Warranted | Number of stamps | 2                 | Axle Combi      | 4x2    |
|           |                           | MOT Due          | 10/11/2025        | Rear Suspension | Steel  |
| Fuel Type | Diesel                    | Cab Type         | CREW CAB          | · · ·           |        |
| Colour    | WHITE                     |                  |                   |                 |        |

#### ALLOY BODY TIPPING GEAR

| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
|-------|------|------|------|------|
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |

### **Features**

Bluetooth connectionDrivers airbag


- Park assist cameraPassenger airbag
- Radio/CDCentral locking
- Front electric windows
- Cloth seat trim

#### Photos





## **Condition Check**



Damage Photos





1: Bonnet Dented Over 30mm

2: Panel Front Dented With Paint Damage







4: Door nsr Chipped Multiple Chips



5: Door nsr Dented With Paint Damage



7: Tailgate Dented Over 30% Of Panel



6: C Post ns Dented With Paint Damage



8: Door osr Chipped Multiple Chips





9: B Post os Rusted Holed





11: Bonnet Chipped Multiple Chips



12: Carpets Rear Soiled Heavy



13: Door Pad nsr Holed Over 3mm



14: Seat Base Cover nsr Soiled Heavy





15: Seat Base Cover osr Torn Over 3mm



17: Door Pad osf Soiled Heavy



19: Fascia Panel Soiled Heavy

Interior



18: Seat Base Cover osf Holed Over 3mm

Holed

Over 3mm

| Carpet Condition<br>Seat Condition | Poor<br>Poor |    | Upholstery Condition<br>Odour | Poor<br>- |    |
|------------------------------------|--------------|----|-------------------------------|-----------|----|
| Engine Runs                        |              | OK | No Excessive Smoking          |           | ОК |
| EML light illuminated              |              | OK | DPF light illuminated         |           | OK |
| ABS light illuminated              |              | OK |                               |           |    |