

VEHICLE INSPECTION REPORT

NU20OZE

Iveco Stralis 460

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	01/06/2020	Colour	GREEN	Gearbox	AUTOMATIC
Year	2020	VIN	WJMS62NT20C421929	Axle Combi	6x2
Mileage	509,662 Km Not Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lif Steert
		Cab Type	HI-WAY CAB	Rear Suspension	Air
Fuel Type	Diesel				

SLIDING 5TH WHEEL

Tyres

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OS03	OSO4	

Features

- Bluetooth connection Air conditioning
- Cruise control
 Front electric windows
- Park assist cameraCloth seat trim
- Digital radio

Photos

















Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Panel Front Poor Previous Repair Rippled UpTo 30%



3: Bumper Front Chipped Multiple Chips



4: Door nsf Scratched Over 25mm Thru Paint



5: Door nsf Chipped Multiple Chips



6: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



7: Door osf Chipped Multiple Chips



8: Screen Front Chipped Over 10mm

Interior

Carpet Condition	OK	Upho	olstery Condition OK	
Seat Condition	OK	Odou	ır -	
Engine Runs		OK No I	Excessive Smoking	OK
EML light illuminated		OK DPF	= light illuminated	OK
ABS light illuminated		OK		