

## **VEHICLE INSPECTION REPORT**

Vehicle

**YO190WH** 

## Ford Transit 350 2.0 TDCI 130PS

Serious Damage?	No	VAI	Plus VA I		
		V5	Buyer To Apply		
Details					
Reg. date	24/04/2019	Colour	WHITE	CAP Average	£3,075.00
Year	2019	VIN	WF0XXXTTGXKK60513	CAP Below	£2,475.00
Mileage	158,283 Miles	Body Style	Panel Van L3	Gearbox	MANUAL
	Warranted	CAP Clean	£3,500.00	Gears	6

#### SIDE LOADING DOOR

Diesel

-		
1/	rο	c
v	16	Э

**Fuel Type** 

Inspection

NSF

NSR

OSF

OSR

Spare

#### **Features**

Park assist camera

· Rear parking sensor

• Front electric windows

#### **Photos**

















# **Condition Check**



## **Damage Photos**



1: Wing osf Scratched Over 25mm Thru Paint



2: Headlamp os Broken Replace



3: Bonnet Dented Between 10mm + 30mm



4: Screen Front Chipped UpTo 10mm



5: Bumper Front Cracked Over 25mm



6: Bumper Front Scratched Over 25mm Not Thru Paint



7: Moulding nsf Wing Scuffed (Unpainted) Over 100mm



8: Door Mirror Glass ns Missing Replace



9: Door Moulding nsf Scuffed (Unpainted) Over 100mm



10: Other N/A N/A



11: Door nsf Chipped Edge Chip



12: Qtr Panel Moulding ns Scuffed (Unpainted) Over 100mm



13: Qtr Panel Moulding ns Scuffed (Unpainted) Over 100mm



14: Qtr Panel Arch Extension ns Scuffed (Unpainted) Over 100mm



15: Qtr Panel Trim ns Scuffed Over 25mm



16: Qtr Panel nsrDentedWith Paint Damage



17: Door osr Dented With Paint Damage



18: Bumper Rear Cracked Over 25mm



19: Qtr Panel osr Dented Over 30% Of Panel



20: Qtr Panel osr Scratched Over 25mm Thru Paint



21: Qtr Panel Trim os Scuffed Over 25mm



22: Qtr Panel Arch Extension os Scuffed (Unpainted) Over 100mm



23: Qtr Panel Trim os Scuffed Over 25mm



24: Qtr Panel Moulding os Scuffed (Unpainted) Over 100mm



25: Qtr Panel osr Dented With Paint Damage



26: Door Moulding osf Scuffed (Unpainted) Over 100mm



27: Moulding osf Wing Scuffed (Unpainted) Over 100mm



28: Other N/A N/A

#### Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average No	
Engine Runs		OK	Gearbox 1st and Revers	e Test	OK
Brakes		OK	Clutch Slip Test from Sta	itic	OK
Parking Brake		OK	Gearbox Static Gear Sel	ection (engine running)	OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illumina	ted	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	minated	OK