

# VEHICLE INSPECTION REPORT

**GM17NTD**

## Volvo FE 320

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 22/06/2017

VIN YV2V001C5HZ110232

Axle Combi 6x4

Year 2017

Body Style Curtainside

Rear Doors Barn

Mileage 394,714 Km Not Warranted

MOT Due 30/06/2025

Tail Lift Tuckaway

Fuel Type Diesel

Cab Type SLEEPER CAB

Colour WHITE

Gearbox AUTOMATIC

\*WARNING LIGHT ON DASH\*

### Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

## Features

- Park assist camera
- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Wing osf  
Scratched  
Over 25mm Not Thru Paint



2: Bumper Front  
Rusted  
Over 5mm





3: Screen Front  
Cracked  
Replace



4: Door Mirror Assy nsf  
Missing  
Replace



5: Door Mirror Assy nsf  
Broken  
Replace



6: Other  
N/A  
N/A



7: Bumper Front  
Rusted  
Over 5mm



8: Door nsr  
Hole  
UpTo 10mm





9: Door osr  
Hole  
UpTo 10mm



10: Other  
N/A  
N/A



11: Other  
N/A  
N/A



12: Other  
N/A  
N/A



13: Door Mirror Assy osf  
Broken  
Replace



14: Seat Base Cover osf  
Torn  
Over 3mm



15: Badgedecal Front  
Missing  
Replace

### Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	Fault		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	