

VEHICLE INSPECTION REPORT

Vehicle

MOT Due

AY18JYD

Mid-Lift

Steering Combi

Mercedes-Benz Actros 2553

Warranted

Diesel

| mapeodon | | Vernoie | | | |
|-----------------|----------------|------------|-------------------|------------|---------------|
| Serious Damage? | No | VAT | Plus VAT | | |
| | | V5 | Present | - - | |
| Details | | | | | |
| Reg. date | 23/03/2018 | Colour | WHITE | Cab Type | GIGASPACE CAB |
| Year | 2018 | VIN | WDB96342320230073 | Gearbox | AUTOMATIC |
| Mileage | 628,731 Km Not | Body Style | Tractor Unit | Axle Combi | 6x2 |

31/08/2025

WARNING LIGHTS ON DASH SLIDING 5TH WHEEL, FRIDGE

Tyres

Fuel Type

Inspection

| NSF | NSI1 | NSI2 | NSI3 | NSI4 | |
|-------|------|------|------|------|--|
| OSF | OSI1 | OSI2 | OSI3 | OSI4 | |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 | |
| | OS01 | OSO2 | OS03 | OSO4 | |

Features

Air conditioning

Photos

















Condition Check



Damage Photos



1: Bumper Front Scratched Over 100mm Thru Paint



2: Bonnet Chipped Multiple Chips



3: Bonnet Missing Replace



4: Screen From Chipped Over 10mm



5: Bumper Front Poor Previous Repair Poor Paint



6: Wing nsf Scratched Over 25mm Thru Paint



7: Door Mirror Assy nsf Scratched (Painted) Over 25mm Thru Paint



8: Other N/A N/A



9: Other N/A N/A



10: Other N/A N/A



11: Other N/A N/A



12: Other N/A N/A



13: Other N/A N/A



14: Other N/A N/A



15: Door nsf Chipped Edge Chip



16: Other N/A N/A



17: Door osf Chipped Over 5mm



18: Other N/A N/A



19: Wing osf Cracked Replace



20: Door Mirror Assy osf Scratched (Painted) Over 25mm Thru Paint



21: Door osf Scratched Over 25mm Thru Paint

Interior

| Carpet Condition Seat Condition | Average Average | | Upholstery Condition Odour | Average - | |
|---------------------------------|--------------------|------------------------------|--|--------------|-------|
| Engine Runs | | OK | Gearbox 1st and Revers | e Test | OK |
| Brakes OK | | Clutch Slip Test from Static | | OK | |
| Parking Brake | | OK | Gearbox Static Gear Selection (engine running) | | OK |
| | | | No Excessive Smoking | | OK |
| EML light illuminated | | Fault | Oil warning light illumina | ted | OK |
| Airbag light illuminated | | OK | DPF light illuminated | | Fault |
| ABS light illuminated | | OK | Service indicator light illu | uminated | OK |