

VEHICLE INSPECTION REPORT



Ford Transit 350 2.0 TDCi 130PS

Inspection	Vehicle	Vehicle		
Serious Damage? No	VAT	Plus VAT		
	V5	Present		

Details

Reg. date	30/09/2017	VIN	WF0XXXTTGXHB69873	CAP Below	£1,925.00
Year	2017	Body Style	Panel Van L3	Gearbox	MANUAL
Mileage	163,045 Miles	MOT Due	24/07/2025	Gears	6
	Warranted	CAP Clean	£3,025.00		
Fuel Type	Diesel	CAP Average	£2.550.00		
Colour	GREEN	<u></u>			

WARNING LIGHT ON DASH AD-BLUE, SIDE LOAD DOOR, TOW BAR, DEADLOCKS

Tyres	
Tyres NSF	
NSR	
OSF	
OSR	
Spare	


Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Auxiliary input socketPassenger airbag
- Digital radio
- Central locking

Photos




Commercial Vehicle Auctions Limited





Condition Check



Damage Photos



1: Bumper Front Scratched Over 100mm Thru Paint



2: Bonnet Chipped Multiple Chips






3: Bonnet Dented Over 30mm



5: Door nsf Chipped Multiple Chips



6: Qtr Panel nsr Dented With Paint Damage

Scratched



7: Qtr Panel nsr Scratched Over 25mm Thru Paint



8: Qtr Panel nsr Dented Over 30mm





9: Qtr Panel nsr Dented Over 30mm

10: Qtr Panel nsr Scratched Over 25mm Thru Paint



11: Qtr Panel Moulding ns Scuffed (Unpainted) Over 100mm



12: Qtr Panel Moulding ns Scuffed (Unpainted) Over 100mm




13: Qtr Panel nsr Scratched Over 25mm Thru Paint



14: Qtr Panel nsr Dented With Paint Damage







17: Qtr Panel osr Dented Over 30mm



19: Qtr Panel osr Scratched Over 25mm Thru Paint



16: Qtr Panel osr Scratched Over 25mm Thru Paint



18: Qtr Panel osr Dented With Paint Damage



20: Qtr Panel osr Scratched Over 25mm Thru Paint






21: Door osf Chipped Multiple Chips



23: Seat Base Cover osf Soiled Heavy





24: Seat Base Cover nsf Soiled Heavy



25: Dash Warning Lights Displayed No Action

Interior

Carpet Condition Seat Condition	OK Poor		Upholstery Condition Odour	Poor -	
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		Fault
ABS light illuminated		ОК			