

VEHICLE INSPECTION REPORT

DK69WHM

Isuzu GRAFTER N35.125

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	18/09/2019	Body Style	Flatbed	Cab Type	DAY CAB
Year	2019	Keys	2	Gearbox	auto
Mileage	204,582 Miles Warranted	MOT Due	08/10/2025	Doors	2
Fuel Type	Diesel	CAP Clean	£4,100.00	Axle Combi	4x2
Colour	WHITE	CAP Average	£3,550.00	Steering Combi	Steer
VIN	JAANLR87EH7102939	CAP Below	£2,850.00	Rear Suspension	Steel

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Carpets Front
Torn
Over 10mm



3: Sill os
Rusted
Over 5mm



4: Bonnet
Rusted
Over 5mm



5: Door osf
Dented
With Paint Damage



6: Qtr Panel osr
Rusted
Over 5mm



7: Tailgate
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Door nsf
Dented
With Paint Damage

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Poor	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	No Excessive Smoking		OK
Parking Brake		OK			
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK