

# **VEHICLE INSPECTION REPORT**

**DP69AXS** 

### Vauxhall Vivaro 2700 1.5d 120PS H1 Dynamic

	Vehicle			
No	VAT	Plus VAT		
	V5	Present		
31/01/2020	VIN	VXEVBYHVKL7014605	CAP Below	£6,150.00
2020	Body Style	Panel Van L1	Gearbox	MANUAL
50,549 Miles Not Warranted	MOT Due	03/10/2025	Gears	6
	CAP Clean	£8,400.00		
Diesel	CAP Average	£7.500.00		
GREY				
	31/01/2020 2020 50,549 Miles Not Warranted Diesel	No         VAT           V5         V5           31/01/2020         VIN           2020         Body Style           50,549 Miles Not Warranted         MOT Due           CAP Clean         CAP Average	No         VAT         Plus VAT           V5         Present           31/01/2020         VIN         VXEVBYHVKL7014605           2020         Body Style         Panel Van L1           50,549 Miles Not Warranted         MOT Due         03/10/2025           CAP Clean         £8,400.00           Diesel         CAP Average         £7,500.00	No         VAT         Plus VAT           V5         Present           31/01/2020         VIN         VXEVBYHVKL7014605         CAP Below           2020         Body Style         Panel Van L1         Gearbox           50,549 Miles Not Warranted         MOT Due         03/10/2025         Gears           Warranted         CAP Clean         £8,400.00           Diesel         CAP Average         £7,500.00

#### AD-BLUE, TWIN SIDE LOAD DOORS, E/MIRRORS

Tyres			
Tyres NSF			
NSR			
OSF			
OSR Spare			
Spare			

### **Features**

- Bluetooth connection
- Air conditioningCentral locking
- Cruise control
- Front electric windows
- Cloth seat trim
- · Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag

#### **Photos**






















## **Condition Check**



### **Damage Photos**



1: Bonnet Chipped Multiple Chips



2: Panel Front Chipped Multiple Chips



3: Wing nsf Scratched Over 25mm Not Thru Paint



4: Door nsf Scratched Over 25mm Thru Paint



5: Door nsf Scratched Over 25mm Thru Paint



6: Door nsf Scratched Over 25mm Thru Paint



7: Qtr Panel nsr Dented Over 30mm



8: Fuel Flap Scratched Over 25mm Thru Paint



9: Qtr Panel nsr Scratched Over 25mm Thru Paint



10: Qtr Panel nsr Scratched Over 25mm Thru Paint



11: Door nsr Dented Over 30mm



12: Door osr Scratched Over 25mm Thru Paint



13: Qtr Panel osr Scratched Over 25mm Thru Paint



14: Qtr Panel osr Scratched Over 25mm Thru Paint



15: Qtr Panel osr Scratched Over 25mm Thru Paint



16: Qtr Panel osr Scratched Over 25mm Thru Paint



17: Qtr Panel osr Scratched Over 25mm Thru Paint



18: Qtr Panel osr Scratched Over 25mm Thru Paint



19: Qtr Panel osr Dented With Paint Damage



20: Door osf Chipped Multiple Chips



21: Wing osf Chipped Multiple Chips

### Interior

Carpet Condition Seat Condition	OK OK		Jpholstery Condition Odour	OK No	
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			