

VEHICLE INSPECTION REPORT

FJ14DCX

Fiat Ducato 35 2.3 MULTIJET 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 25/04/2014

Year 2014

Mileage 103,898 Miles
Warranted

Fuel Type Diesel

Colour RED

VIN ZFA25000002516898

Body Style Tipper

MOT Due 05/06/2026

Gearbox AUTOMATIC

Gears 6

TWIN SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR



Spare

Features

- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Door Mirror Assy nsf
Broken
Replace



3: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door osf
Scratched
Over 25mm Thru Paint



7: Door osf
Dented
With Paint Damage



8: Screen Front
Chipped
UpTo 10mm



9: Panel Front
Scratched
Over 25mm Thru Paint



10: Seat Base Cover osf
Holed
Over 3mm



11: Carpets Front
Holed
Over 3mm



12: Door Pad osf
Soiled
Heavy



13: Seat Base Cover nsf
Soiled
Heavy



14: Door Pad nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		