

VEHICLE INSPECTION REPORT

DF64GSV

Mercedes-Benz Antos 1824

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 02/01/2015

VIN WDB9630032L907744

Axle Combi 4x2

Year 2015

Body Style Curtainside

Rear Suspension Steel

Mileage 297,754 Km Not Warranted

MOT Due 31/08/2025

Rear Doors Barn

Fuel Type Diesel

Cab Type DAY CAB

Tail Lift Tuckaway

Colour WHITE

Gearbox AUTOMATIC

SURROUND CAMERA SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features


- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: Bumper Front
Cracked
Over 25mm



2: Bumper Front
Cracked
Over 25mm



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Bumper Front
Cracked
Over 25mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Other
N/A
N/A



7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



8: Other
N/A
N/A



9: Other
N/A
N/A



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



13: Other
N/A
N/A



14: Other
N/A
N/A



15: Other
N/A
N/A

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK