

VEHICLE INSPECTION REPORT

EJ20VLU

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 30/07/2020

Year 2020

Mileage 80,887 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WDB9101332N039146

Body Style Curtainside L2

MOT Due 18/08/2025

CAP Clean £15,750.00

CAP Average £14,050.00

CAP Below £11,500.00

Gearbox MANUAL

Tail Lift Column

WARNING LIGHT ON DASH AD BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing osf
Dented
With Paint Damage



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Grille Front
Broken
Replace



5: Bonnet
Dented
With Paint Damage



6: Screen Front
Cracked
Replace



7: Wing nsf
Dented
With Paint Damage



8: Door Mirror Assy nsf
Missing
Replace

Email: jamesgibbard@live.com

9: Other
N/A
N/A



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Door osf
Dented
Over 2 UpTo 10mm



13: Door Mirror Assy osf
Broken
Replace



14: Door osf
Dented
With Paint Damage



15: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK