

VEHICLE INSPECTION REPORT

AY18JYE

Mercedes-Benz Actros 2553

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 23/03/2018

VIN WDB96342320230074

Axle Combi 6x2

Year 2018

Body Style Tractor Unit

Steering Combi Mid-Lift

Mileage 753,503 Km Not Warranted

MOT Due 30/09/2025

Rear Suspension Air

Fuel Type Diesel

Cab Type BIGSPACE CAB

Colour WHITE

Gearbox AUTOMATIC

WARNING LIGHT ON DASH FRIDGE, SLIDING 5TH WHEEL

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Other
N/A
N/A



3: Bonnet
Chipped
Multiple Chips



4: Screen Front
Chipped
Over 10mm



5: Bumper Front
Cracked
Over 25mm



6: Door nsf
Dented
Over 30mm



7: Other
N/A
N/A



8: Wing nsf
Poor Previous Repair
Poor Paint



9: Door Mirror Assy nsf
Broken
Replace



10: Door Mirror Assy nsf
Missing
Replace



11: Other
N/A
N/A



12: Other
N/A
N/A



13: Door osf
Dented
With Paint Damage



14: Other
N/A
N/A



15: Other
N/A
N/A

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	Fault
ABS light illuminated	OK		Service indicator light illuminated	OK