

# VEHICLE INSPECTION REPORT

**DK18HXG**

## Daf LF 180

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date	05/03/2018	VIN	XLRAEL1500L472858	Gearbox	Automatic
Year	2018	Body Style	Box Van	Axle Combi	4x2
Mileage	561,811 Km Warranted	Keys	3	Steering Combi	Steer
Fuel Type	Diesel	MOT Due	30/04/2026	Rear Suspension	Steel
Colour	WHITE	Cab Type	SLEEPER CAB	Rear Doors	Barn


### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Drivers airbag
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Torn  
Over 3mm



2: Carpets Front  
Torn  
Over 10mm



3: Door Moulding osf  
Scuffed (Unpainted)  
Over 100mm



4: Bonnet  
Scratched  
Over 25mm Thru Paint



5: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



6: Door osf  
Dented  
With Paint Damage



7: Tailgate  
Rusted  
Over 5mm



8: Qtr Panel nsr  
Hole  
UpTo 10mm



9: Door osf  
Dented  
Over 30mm



10: Door Moulding nsf  
Missing  
Replace



11: A Post ns  
Rusted  
Over 5mm

### Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK