

VEHICLE INSPECTION REPORT

C376749

Cartwright BOX DOUBLE DECK

Inspection

Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details

Reg. date	01/01/2014	VIN	SMWCV39SFEA140731	Steering Combi	Rear Steer
Year	2014	Body Style	Trailer	Rear Suspension	Air
Mileage	TBC	MOT Due	31/10/2025	Rear Doors	Roller
Fuel Type		Brakes	Disc		
Colour	RED	Axle Combi	Tri		

BATTERY, ROPES, BRAKES REQ. ATTN. BPW AXLES


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos



Condition Check



Damage Photos



1: Qtr Panel osr
Dented
With Paint Damage



2: Tailgate
Rusted
Over 5mm



3: Qtr Panel nsr
Dented
With Paint Damage



4: Bonnet
Rusted
Over 5mm

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -