

# VEHICLE INSPECTION REPORT

**NK150EE**

## Mercedes-Benz Econic

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 24/03/2015

Year 2015

Mileage 155,239 Km Not Warranted

Fuel Type Diesel

Colour BLACK

VIN WDB9560332V238421

Body Style Dropside

MOT Due 30/11/2025

Cab Type CREW CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Rear-Lift Steer

Rear Suspension Steel

\*WARNING LIGHT ON DASH\*

### Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4


## Features

- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Fog Lamp Surround os  
Scratched (Painted)  
Over 25mm Thru Paint



2: Bumper Front  
Cracked  
UpTo 25mm





3: Fog Lamp Surround ns  
Broken  
Replace



4: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



5: Door nsf  
Scratched  
UpTo 25mm Thru Paint



6: Door nsf  
Scratched  
UpTo 25mm Thru Paint



7: Door nsf  
Chipped  
Edge Chip



8: Other  
N/A  
N/A





9: Bumper Rear  
Rusted  
Over 5mm



10: Door osf  
Scratched  
Over 25mm Thru Paint



11: Door osf  
Chipped  
Edge Chip



12: Seat Base Cover osf  
Torn  
Over 3mm



13: Fascia Panel  
Broken  
Replace



14: Seat Base Cover nsf  
Burn  
Over 3mm

## Interior

<b>Carpet Condition</b>	<b>Average</b>	<b>Upholstery Condition</b>	<b>Average</b>
<b>Seat Condition</b>	<b>Average</b>	<b>Odour</b>	<b>-</b>
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK