

# VEHICLE INSPECTION REPORT

**YD19AOC**

## Fiat Ducato 35 2.3 MULTIJET 130PS

**Non Runner**  
Inspection

<b>Serious Damage?</b>	No	<b>Vehicle</b>	
		<b>VAT</b>	Plus VAT
		<b>V5</b>	Present

### Details

<b>Reg. date</b>	26/06/2019	<b>Colour</b>	WHITE	<b>MOT Due</b>	Expired
<b>Year</b>	2019	<b>VIN</b>	ZFA25000002J25796	<b>Gearbox</b>	MANUAL
<b>Mileage</b>	178,391 Miles Warranted	<b>Body Style</b>	Luton	<b>Gears</b>	6
<b>Fuel Type</b>	Diesel	<b>Number of stamps</b>	8	<b>Tail Lift</b>	Column

\*NON RUNNER - TURNS OVER WILL NOT START\* \*WARNING LIGHT ON DASH\* CURTAINSIDES, E/ MIRRORS

### Tyres

NSF

NSR

OSF

OSR

Spare


## Features

- Bluetooth connection
- Digital radio
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

## Photos












## Condition Check



## Damage Photos



1: Bumper Front  
Scratched  
Over 100mm Thru Paint



2: Bonnet  
Dented  
With Paint Damage





3: Panel Front  
Scratched  
Over 25mm Thru Paint



4: Bumper Front  
Scratched  
Over 100mm Thru Paint



5: Door nsf  
Dented  
Over 30mm



6: Door nsf  
Dented  
Over 30mm



7: Qtr Panel nsr  
Hole  
Over 10mm



8: Qtr Panel osr  
Hole  
Over 10mm



9: Qtr Panel Trim os  
Scuffed  
Over 25mm



10: Carpets Front  
Holed  
Over 3mm



11: Seat Base Cover osf  
Torn  
Over 3mm

Interior

Carpets Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs		Fault	