

VEHICLE INSPECTION REPORT

LT68FYU

Fuso Canter 7C15

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 28/09/2018

Colour WHITE

Gearbox AUTOMATIC

Year 2018

VIN TYAFEB71GRDZ10044

Axle Combi 4x2

Mileage 75,355 Km Warranted

Body Style Tipper

Rear Suspension Steel

Fuel Type Diesel

Cab Type DAY CAB

SPENBOROUGH STEEL BODY TIPPING GEAR, SURROUND CAMERA SYSTEM, WEIGH SYSTEM, WACKER PLATE LIFT ON N/S

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Radio/CD
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Digital radio
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Door nsf
Dented
Over 30mm



5: Door nsf
Dented
With Paint Damage



6: Door Pad osf
Soiled
Heavy



7: Seat Base Cover osf
Torn
Over 3mm



8: Carpets Front
Soiled
Heavy



9: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		Upholstery Condition	
Poor		Poor	
Seat Condition		Odour	
Poor		-	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		