

VEHICLE INSPECTION REPORT

LT68FZY

Fuso Canter 7C15

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 08/11/2018

Colour WHITE

Gearbox AUTOMATIC

Year 2018

VIN TYAFEB71GRDZ10424

Axle Combi 4x2

Mileage 72,433 Km Warranted

Body Style Tipper

Rear Suspension Steel

Fuel Type Diesel

Cab Type DAY CAB

SPENBOROUGH STEEL BODY TIPPING GEAR, WEIGH SYSTEM, WACKER PLATE LIFT ON N/S

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Park assist camera
- Passenger airbag
- Radio/CD
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Chipped
Multiple Chips



3: Door osf
Dented
Over 30mm



4: Door osf
Dented
With Paint Damage



5: Door osf
Chipped
Multiple Chips



6: Door Pad osf
Soiled
Heavy



7: Seat Base Cover osf
Torn
Over 3mm



8: Carpets Front
Soiled
Heavy



9: Fascia Panel
Broken
Replace



10: Seat Base Cover nsf
Soiled
Heavy



11: Door Pad nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		