

VEHICLE INSPECTION REPORT

WU67JCO

Mercedes-Benz Arocs 1824

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 03/01/2018

Year 2018

Mileage 127,820 Km Not Warranted

Fuel Type Diesel

Colour ORANGE

VIN WDB96420020198246

Body Style Skiploader

MOT Due 31/08/2025

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Steel

WARNING LIGHT ON DASH HYVA NG 2012 XL GEAR, SHEETING SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features


- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Fog Lamp Surround is
Broken
Replace



3: Moulding of Wing
Scratched (Painted)
Up To 25mm Thru Paint



4: Other
N/A
N/A



5: Fog Lamp Surround ns
Broken
Replace



6: Bumper Front
Dented
Between 10mm + 30mm



7: Other
N/A
N/A



8: Door Mirror Assy nsf
Broken
Replace



9: Other
N/A
N/A



10: Other
N/A
N/A



11: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



12: Door osf
Dented
With Paint Damage



13: Other
N/A
N/A



14: Seat Base Cover osf
Holed
Over 3mm



15: Other
N/A
N/A

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Average	Average	Average	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK