

# VEHICLE INSPECTION REPORT

**YJ13HUV**

## Vdl Futura FHD2-129

### Serious Damage Inspection

Serious Damage? Yes

### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

### Details

Reg. date	17/04/2013	Colour	WHITE	Cab Type	DAY CAB
Year	2013	VIN	XNL501E100D002274	Gearbox	AUTOMATIC
Mileage	743,959 Km Not Warranted	Body Style	Coach	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/10/2025	Rear Suspension	Air

\*WARNING LIGHT ON DASH, TWO SMASHED WINDOW PANELS, NO ACCESS TO TOILET, W/CHAIR LIFT INOPERABLE\* 49 SEATS + 1 WHEELCHAIR, DRIVER & CREW SEAT, PANEL SYSTEM, ENTERTAINMENT SYSTEM, UNDERBODY STORAGE, OVERHEAD STOWAGE, RECLINING SEATS, REAR EXIT

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


## Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Cloth seat trim
- Digital radio
- Radio/CD



## Photos
















## Condition Check



## Damage Photos



1: Screen Front  
Cracked  
Replace




2: Door Mirror Assy nsf  
Broken  
Replace



3: Door nsf  
 Scratched  
 Over 25mm Thru Paint



4: Qtr Panel nsr  
 Scratched  
 Over 25mm Not Thru Paint



5: Qtr Panel nsr  
 Scratched  
 Over 25mm Thru Paint



6: Qtr Panel nsr  
 Scratched  
 Over 25mm Thru Paint



7: Qtr Panel nsr  
 Scratched  
 Over 25mm Thru Paint



8: Qtr Panel nsr  
 Dented  
 Over 30mm



9: B Post ns  
Cracked  
Replace



10: Qtr Panel osr  
Dented  
With Paint Damage



11: Door osr  
Dented  
With Paint Damage



12: Qtr Panel osr  
Dented  
Over 30mm



13: Door Window osr  
Missing  
Replace



14: Door Window osr  
Missing  
Replace



15: Door Mirror Assy osf  
Broken  
Replace



16: Seat Base Cover osf  
Holed  
Over 3mm

**Interior**

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	Poor	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		