

VEHICLE INSPECTION REPORT

DK66KAX

Man TGS 26.360

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	23/01/2017	VIN	WMA18SZZXHP083629	Axle Combi	6x2
Year	2017	Body Style	Dropside & Crane	Steering Combi	Rear-Lift Steer
Mileage	132,708 Km Warranted	MOT Due	30/11/2025	Rear Suspension	Steel
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	BLUE	Gearbox	MANUAL		

HMF 1420 K2 REMOTE CRANE (YEAR 2016), SURROUND CAMERA SYSTEM, SERVICE SCHEDULE LIST AVAILABLE

Tyres

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NS01	NSO2	NSO3	NSO4	
	OS01	OSO2	OSO3	OSO4	

Features

Park assist camera

Photos

















Condition Check



Damage Photos



1: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



2: Fog Lamp Surround os Scuffed (Unpainted) UpTo 100mm



3: Wing osf Scratched UpTo 25mm Thru Paint



4: Screen Front Chipped UpTo 10mm



5: Bumper Front Cracked UpTo 25mm



6: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



7: Fog Lamp Surround ns Scuffed (Unpainted) UpTo 100mm



8: Door Mirror Assy nsf Missing Replace



9: Door Mirror Assy nsf Scuffed (Unpainted) UpTo 100mm



10: Other N/A N/A



11: Other N/A N/A



12: Other N/A N/A



13: Qtr Panel nsr Dented Over 30mm



14: Bumper Rear Rusted Over 5mm



15: Qtr Panel osr Dented Over 30mm



16: Other N/A N/A



17: Other N/A N/A



18: Other N/A N/A



19: Other N/A N/A



20: Door Mirror Assy osf Scuffed (Unpainted) UpTo 100mm



21: Other N/A N/A



22: Door Pad osf Broken Replace

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Average Odour -	
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK