

VEHICLE INSPECTION REPORT

HX16FXK

Mercedes-Benz Antos 1824

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 31/03/2016

VIN WDB96300320020378

Cab Type DAY CAB

Year 2016

Body Style Flatbed & Crane

Gearbox AUTOMATIC

Mileage 410,916 Km Warranted

Service history Yes

Rear Suspension Air

Fuel Type Diesel

Service documents Electronic / Online

Colour WHITE

MOT Due 31/10/2025

PALFINGER PK 18002-EH REMOTE CRANE (YEAR 2015), FSH & LAST CRANE TEST AVAILABLE

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Digital radio
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Central locking


Photos







Condition Check



Damage Photos



1: Qtr Panel osr
Dented
Over 30% Of Panel



2: Wing osf
Chipped
Multiple Chips



3: Bumper Front Moulding
Broken
Replace



4: Bumper Front
Cracked
Over 25mm



5: Bonnet
Chipped
Multiple Chips



6: Bumper Front Moulding
Broken
Replace



7: Wing nsf
Chipped
Multiple Chips



8: Roof
Dented
Over 30mm



9: Seat Base Cover nsf
Soiled
Heavy



10: Door osf
Dented
With Paint Damage



11: Door osf
Chipped
Multiple Chips



12: Door osf
Dented
With Paint Damage

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		