

## VEHICLE INSPECTION REPORT

**BV67GSU**

### Volkswagen Crafter CR35 2.0 TDI BMT 109PS

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Present

#### Details

Reg. date 29/09/2017

VIN WV1ZZZ2EZG6062920

CAP Below £2,300.00

Year 2017

Body Style Panel Van MWB

Gearbox MANUAL

Mileage 142,316 Miles Not Warranted

MOT Due 01/10/2025

Gears 6

Fuel Type Diesel

CAP Clean £3,550.00

Colour WHITE

CAP Average £3,000.00

SIDE LOAD DOOR, E/ MIRRORS, TOW BAR, DEADLOCKS (WITH KEYS)

#### Tyres

NSF

NSR

OSF

OSR

Spare

### Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Rear parking sensor
- Passenger airbag
- Digital radio
- Central locking

### Photos












## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips




2: Roof  
Chipped  
Multiple Chips



3: Bumper Front  
Hole  
UpTo 25mm



4: Wing nsf  
Dented  
Over 30mm



5: Door nsf  
Scratched  
Over 25mm Thru Paint



6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsf  
Dented  
Over 30mm



8: Door Moulding nsf  
Scuffed (Unpainted)  
Over 100mm





9: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



10: Sill ns  
Dented  
With Paint Damage



11: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



12: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



13: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



14: Bumper Rear Moulding  
Scuffed (Unpainted)  
Over 100mm



15: Door nsr  
Dented  
Over 30mm




16: Door osr  
Dented  
Over 30mm



17: Qtr Panel osr  
Rusted  
Over 5mm



18: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm



19: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



20: Qtr Panel osr  
Dented  
Over 30mm





21: Qtr Panel osr  
Chipped  
Multiple Chips



22: Qtr Panel osr  
Dented  
Over 30mm



23: B Post os  
Dented  
Over 30mm



24: Door osf  
Chipped  
Multiple Chips



25: Screen Front  
Chipped  
Over 10mm



26: Seat Base Cover osf  
Torn  
Over 3mm





27: Seat Base Cover nsf  
Burn  
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		