

VEHICLE INSPECTION REPORT

DX19XHM

Daf LF 180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	05/06/2019	VIN	XLRAEL1500L485833	Axle Combi	4x2
Year	2019	Body Style	Box Van	Rear Suspension	Steel
Mileage	161,680 Km Warranted	MOT Due	30/09/2025	Rear Doors	Roller
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Column
Colour	WHITE	Gearbox	MANUAL		

WARNING LIGHT ON DASH


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Digital radio
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Panel Front
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Dented
With Paint Damage



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Door osf
Scratched
Over 25mm Thru Paint



9: Door osf
Scratched
Over 25mm Thru Paint



10: Door Pad osf
Soiled
Heavy



11: Seat Base Cover osf
Torn
Over 3mm



12: Seat Base Cover nsf
Soiled
Heavy



13: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		