

# VEHICLE INSPECTION REPORT

**YC19LZN**

## Volvo FM 410

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

|           |                      |            |                   |                 |           |
|-----------|----------------------|------------|-------------------|-----------------|-----------|
| Reg. date | 10/06/2019           | Colour     | WHITE             | Gearbox         | AUTOMATIC |
| Year      | 2019                 | VIN        | YV2XZ22GXJB867153 | Axle Combi      | 8x4       |
| Mileage   | 127,335 Km Warranted | Body Style | Tipper Grab       | Rear Suspension | Steel     |
| Fuel Type | Diesel               | Cab Type   | DAY CAB           |                 |           |

PALFINGER EPSILON M125L CLASSIC CRANE (YEAR 2019), SURROUND CAMERA SYSTEM, SHEETING SYSTEM

### Tyres

|       |      |      |      |      |
|-------|------|------|------|------|
| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |


## Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Partial leather seat trim

## Photos














## Condition Check



## Damage Photos



1: Bumper Front  
Dented  
With Paint Damage



2: Bumper Front  
Dented  
With Paint Damage



3: Door nsf  
 Scratched  
 Over 25mm Thru Paint



4: Seat Base Cover osf  
 Torn  
 Over 3mm

**Interior**

|                         |    |      |                             |    |    |
|-------------------------|----|------|-----------------------------|----|----|
| <b>Carpet Condition</b> |    | OK   | <b>Upholstery Condition</b> |    | OK |
| <b>Seat Condition</b>   |    | Poor | <b>Odour</b>                |    | -  |
| Engine Runs             | OK |      | No Excessive Smoking        | OK |    |
| EML light illuminated   | OK |      | DPF light illuminated       | OK |    |
| ABS light illuminated   | OK |      |                             |    |    |