

VEHICLE INSPECTION REPORT

Vehicle

WU68NXY

Volvo FH 460

Inspection

Serious Damage?	No	VAT	Plus VAT		
		V5	Buyer To Apply		
Details					
Reg. date	01/12/2018	Colour	WHITE	Gearbox	AUTOMATIC
Year	2018	VIN	YV2RTY0C6KA838236	Axle Combi	6x2
Mileage	1,067,241 Km Not Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift
		Cab Type	GLOBETROTTER	Rear Suspension	Air
Fuel Type	Diesel		CAB	· · ·	

WARNING LIGHT ON DASH

Tyres

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	_
	OS01	OSO2	OS03	OSO4	_

Features

- Bluetooth connection · Air conditioning
- Cruise control
 Front electric windows
- Auxiliary input socketCentral locking
- Digital radioCloth seat trim

Photos































Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Bumper Front Scratched Over 100mm Thru Paint



3: Panel Front Scratched Over 25mm Thru Paint



4: Door nsf Dented With Paint Damage



5: Door nsf Scratched UpTo 25mm Not Thru Paint



6: Door nsf Dented Over 30mm




7: Door nsf Scratched Over 25mm Not Thru Paint



8: Door nsf Chipped Multiple Chips



9: Qtr Panel Trim ns Scuffed Over 25mm



10: Qtr Panel osr Dented With Paint Damage



11: Door osf Chipped Multiple Chips



12: Door osf Scratched Over 25mm Thru Paint



13: Panel Front Poor Previous Repair Poor Colour



14: Bumper Front Scratched Over 100mm Thru Paint



15: Door Pad osf Soiled Heavy

Interior

Carpet Condition	OK	Upholstery Condi	ition Poor	
Seat Condition	OK	Odour	-	
Engine Runs		OK No Excessive Sn	moking	OK
EML light illuminated		OK DPF light illumina	ated	OK
ABS light illuminated		OK		