

VEHICLE INSPECTION REPORT

PN61PKZ

Daf CF 75.310

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 28/09/2011

Year 2011

Mileage 504,614 Km Not Warranted

Fuel Type Diesel

Colour BLUE

VIN XLRAS75PC0E915973

Body Style Beavertail

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Rear Suspension Air

WARNING LIGHT ON DASH *DOES NOT CHANGE GEAR* SURROUND CAMERA SYSTEM, REAR LIFT, WINCH

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Radio/CD
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage



3: Bumper Front
Chipped
Multiple Chips



4: Bumper Front
Dented
With Paint Damage



5: Bumper Front
Scratched
Over 100mm Thru Paint



6: Bumper Front Moulding
Broken
Replace



7: Door Mirror Assy nsf
Broken
Replace



8: Lamp nsr
Broken
Replace



9: Panel Front
Cracked
Replace



10: Door osf
Chipped
Multiple Chips



11: Screen Front
Chipped
Over 10mm



12: Carpets Front
Torn
Over 10mm



13: Seat Base Cover osf
Torn
Over 3mm



14: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK		
ABS light illuminated	OK		