

VEHICLE INSPECTION REPORT

HK71PXU

Ford Transit 350 2.0 ECOBLUE 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 22/11/2021

Year 2021

Mileage 79,168 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0EXXTTREM09512

Body Style Panel Van L3

MOT Due 25/11/2025

CAP Clean £7,950.00

CAP Average £7,200.00

CAP Below £6,075.00

Gearbox MANUAL

Gears 6

CRACK IN WINDSCREEN AD-BLUE, SIDE LOAD DOOR, TOW BAR, DEADLOCKS (WITH KEYS), BUYER TO PURCHASE NUMBER PLATES

Tyres

NSF

NSR

OSF

OSR



Spare


Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Front parking sensor
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Number Plate Front
Missing
Replace



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Panel Front
Scratched
Over 25mm Thru Paint



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Wing nsf
Dented
Over 30mm



8: Door Mirror Assy nsf
Broken
Replace



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Door nsf
Scratched
Over 25mm Thru Paint



11: Door nsf
Scratched
Over 25mm Thru Paint



12: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



13: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



14: Fuel Flap
Scratched
Over 25mm Thru Paint



15: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



16: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



17: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



18: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



19: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



20: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



21: Qtr Panel nsr
Dented
Over 30mm



22: Qtr Panel nsr
Dented
With Paint Damage



23: Qtr Panel nsr
Dented
With Paint Damage



24: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



25: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



26: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



27: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



28: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



29: Qtr Panel nsr
Dented
With Paint Damage



30: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



31: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



32: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



33: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



34: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



35: C Post ns
Scratched
Over 25mm Thru Paint



36: Bumper Rear Moulding
Broken
Replace



37: Number Plate Rear
Missing
Replace



38: Door nsr
Scratched
Over 25mm Thru Paint



39: Door osr
Dented
Over 30mm



40: Door osr
Dented
Over 30mm



41: Door Moulding osr
Broken
Replace



42: Bumper Rear Moulding
Broken
Replace



43: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



44: C Post os
Scratched
Over 25mm Thru Paint



45: C Post os
Scratched
Over 25mm Thru Paint



46: Qtr Panel osr
Scratched
Over 25mm Thru Paint



47: Qtr Panel osr
Scratched
Over 25mm Thru Paint



48: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



49: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



50: Qtr Panel osr
Scratched
Over 25mm Thru Paint



51: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



52: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



53: Door Mirror Assy osf
Broken
Replace



54: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



55: Panel Front
Scratched
Over 25mm Thru Paint



56: Bumper Front
Scratched
Over 100mm Thru Paint



57: Bumper Front
Dented
With Paint Damage



58: Screen Front
Cracked
Replace



59: Door Pad nsf
Soiled
Heavy



60: Seat Base Cover nsf
Soiled
Heavy



61: Seat Back Cover nsf
Soiled
Heavy



62: Seat Base Cover nsf
Soiled
Heavy



63: Seat Back Cover nsf
Soiled
Heavy



64: Seat Back Cover osf
Soiled
Heavy



65: Seat Base Cover osf
Soiled
Heavy



66: Glove Box Lid
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		