

VEHICLE INSPECTION REPORT

YF71GVR

Maxus Deliver 3

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 28/02/2022

Year 2022

Mileage 44,358 Miles Not Warranted

Fuel Type ELECTRIC

Colour WHITE

VIN LSH14C4C9MA050619

Body Style Panel Van L1

CAP Clean £5,950.00

CAP Average £5,525.00

CAP Below £4,750.00

Gearbox AUTOMATIC

Gears 1

WARNING LIGHT ON DASH SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR


Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bumper Front
Cracked
Over 25mm



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Panel Front
Scratched
Over 25mm Thru Paint



4: Panel Front
Cracked
Replace



5: Panel Front
Scratched
Over 25mm Thru Paint



6: Door Mirror Assy nsf
Broken
Replace



7: Qtr Panel nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Dented
With Paint Damage



10: Bumper Rear
Cracked
Over 25mm



11: Door nsr
Dented
With Paint Damage



12: Door nsr
Dented
With Paint Damage



13: Door nsr
Dented
With Paint Damage



14: Door nsr
Dented
Over 30mm



15: Door nsr
Dented
With Paint Damage



16: Door osr
Dented
With Paint Damage



17: Qtr Panel Moulding os
Broken
Replace



18: Qtr Panel osr
Scratched
Over 25mm Thru Paint




19: Qtr Panel osr
Dented
With Paint Damage



20: Qtr Panel osr
Scratched
Over 25mm Thru Paint



21: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



22: Qtr Panel osr
Scratched
Over 25mm Thru Paint



23: Door osf
Dented
Over 30mm



24: Seat Base Cover osf
Burn
Over 3mm



25: Seat Base Cover nsf
Soiled
Heavy



26: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault		