

# VEHICLE INSPECTION REPORT

**YF71GVX**

## Maxus Deliver 3 90KW 35KWH

**Non Runner** **Serious Damage**  
Inspection

Serious Damage? Yes

### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

### Details

|           |                            |            |                   |             |           |
|-----------|----------------------------|------------|-------------------|-------------|-----------|
| Reg. date | 28/02/2022                 | Colour     | WHITE             | CAP Average | £5,700.00 |
| Year      | 2022                       | VIN        | LSH14C4C6MA050514 | CAP Below   | £4,900.00 |
| Mileage   | 38,398 Miles Not Warranted | Body Style | Panel Van L1      | Gearbox     | AUTOMATIC |
| Fuel Type | Electric                   | CAP Clean  | £6,150.00         | Gears       | 1         |

\*NON RUNNER - PARTS STRIPPED\*

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag

## Photos












## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Soiled  
Heavy



2: Seat Base Cover nsf  
Soiled  
Heavy



3: Fascia Panel  
Soiled  
Heavy



4: Unclassified  
Substantial Accident Damage  
Report Only



5: Unclassified  
Major Parts Missing  
Report Only



6: Unclassified  
Major Parts Missing  
Report Only



7: Wheel osf  
Damaged  
Replace



8: Door osf  
Missing  
Replace





9: Door Moulding osf  
Broken  
Replace



10: Qtr Panel Moulding os  
Broken  
Replace



11: Qtr Panel osr  
Chipped  
Multiple Chips



12: Qtr Panel osr  
Dented  
With Paint Damage



13: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



14: Qtr Panel osr  
Dented  
With Paint Damage



15: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



16: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



17: C Post os  
Scratched  
Over 25mm Thru Paint



18: Lamp osr  
Missing  
Replace



19: Door osr  
Dented  
Over 30% Of Panel



20: Bumper Rear  
Dented  
Over 30% Of Panel





21: Door nsr  
Dented  
Over 30% Of Panel



22: Door nsr  
Dented  
With Paint Damage



23: Lamp nsr  
Missing  
Replace



24: C Post ns  
Scratched  
Over 25mm Thru Paint



25: Qtr Panel nsr  
Poor Previous Repair  
Rippled UpTo 30%



26: Qtr Panel nsr  
Poor Previous Repair  
Rippled UpTo 30%





27: Qtr Panel nsr  
Poor Previous Repair  
Rippled Over 30%



28: Qtr Panel nsr  
Dented  
Over 30mm



29: B Post ns  
Scratched  
Over 25mm Thru Paint



30: Door nsf  
Dented  
Over 30mm



31: Door Mirror Assy nsf  
Broken  
Replace

## Interior

|                  |       |                      |      |
|------------------|-------|----------------------|------|
| Carpet Condition | OK    | Upholstery Condition | Poor |
| Seat Condition   | Poor  | Odour                | No   |
| Engine Runs      | Fault |                      |      |