

VEHICLE INSPECTION REPORT

YD68ZKP

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date 06/09/2018

Year 2018

Mileage 158,554 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WDB9061352N767660

Body Style Dropside LWB

MOT Due 07/01/2026

CAP Clean £5,250.00

CAP Average £4,525.00

CAP Below £3,525.00

Gearbox MANUAL

Tail Lift Column

WARNING LIGHT ON DASH AD BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Other
N/A
N/A



4: Bonnet
Chipped
Multiple Chips



5: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



6: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



7: Wing nsf
Scratched
UpTo 25mm Thru Paint



8: Wing nsf
Scratched
UpTo 25mm Thru Paint



9: Door nsf
Dented
Between 10mm + 30mm



10: Moulding nsf Wing
Scuffed (Unpainted)
UpTo 100mm



11: Door Moulding nsf
Scuffed (Unpainted)
UpTo 100mm



12: Door osf
Scratched
Over 25mm Thru Paint



13: Door Mirror Assy osf
Missing
Replace



14: Door Mirror Glass os
Missing
Replace



15: Sill os
Rusted
Over 5mm



16: Other
N/A
N/A



17: Other
N/A
N/A



18: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	Fault		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	Fault	