

# VEHICLE INSPECTION REPORT

**PF14TZA**

## Daf LF 150

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 27/08/2014

VIN XLRAEL1500L437979

Gearbox MANUAL

Year 2014

Body Style Box Van

Axle Combi 4x2

Mileage 662,613 Km Warranted

Service history Yes

Tail Lift Cantilever

Fuel Type Diesel

MOT Due 30/09/2025

Colour RED

Cab Type DAY CAB

\*COLLECTED AS NON RUNNER - DIFF., MOTOR & SHOCKS REQ. ATTN.\*

### Tyres


NSF NSI1 NSI2 NSI3 NSI4



OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4


### Photos







## Condition Check



## Damage Photos



1: Wing osf  
Scratched  
Over 25mm Thru Paint



2: Bumper Front Moulding  
Scratched (Painted)  
UpTo 25mm Thru Paint



3: Screen Front  
Chipped  
Over 10mm



4: Bumper Front Moulding  
Scratched (Painted)  
UpTo 25mm Thru Paint



5: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



6: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm



7: Other  
N/A  
N/A



8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint





9: Bumper Rear  
Rusted  
Over 5mm



10: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



11: Door osf  
Chipped  
Edge Chip



12: Door osf  
Scratched  
UpTo 25mm Thru Paint



13: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm



14: Seat Base Cover nsf  
Holed  
Over 3mm



15: Other  
N/A  
N/A



16: Other  
N/A  
N/A



17: Other  
N/A  
N/A

## Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK