

VEHICLE INSPECTION REPORT

PF66KKJ

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 23/11/2016

VIN XLRTGM4100G134739

Gearbox AUTOMATIC

Year 2016

Body Style Tractor Unit

Axle Combi 6x2

Mileage 1,393,404 Km
Warranted

Service history Yes

Steering Combi Mid-Lift Steer

MOT Due 30/09/2025

Rear Suspension Air

Fuel Type Diesel

Cab Type SLEEPER CAB

Colour RED

COLLECTED AS NON RUNNER, NEW ENGINE REQUIRED N/S CAMERA

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scratched (Painted)
UpTo 25mm Thru Paint



2: Other
N/A
N/A



3: Wing osf
Chipped
Multiple Chips



4: Bonnet
Chipped
Multiple Chips



5: Front TowEye Cvr
Missing
Replace



6: Bumper Front
Rusted
Over 5mm



7: Bumper Front Moulding
Scratched (Painted)
UpTo 25mm Thru Paint



8: Other
N/A
N/A



9: Wing nsf
Chipped
Multiple Chips



10: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



11: Door nsf
Scratched
UpTo 25mm Thru Paint



12: Other
N/A
N/A



13: Other
N/A
N/A



14: Door osf
Scratched
Over 25mm Thru Paint



15: Other
N/A
N/A



16: Door Mirror Assy osf
Broken
Replace



17: Other
N/A
N/A



18: Other
N/A
N/A



19: Other
N/A
N/A

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK