

# VEHICLE INSPECTION REPORT

**DV73PVF**

## Vauxhall Vivaro 3100 2.0 D 145PS

**Non Runner  
Inspection**

<b>Serious Damage?</b>	No	<b>Vehicle</b>	
		<b>VAT</b>	Plus VAT
		<b>V5</b>	Buyer To Apply

### Details

<b>Reg. date</b>	27/09/2023	<b>VIN</b>	VXEVEHTMP7856859	<b>CAP Below</b>	£11,200.00
<b>Year</b>	2023	<b>Body Style</b>	Panel Van L2	<b>Gearbox</b>	MANUAL
<b>Mileage</b>	19,255 Miles Not Warranted	<b>MOT Due</b>	26/09/2026	<b>Gears</b>	6
<b>Fuel Type</b>	Diesel	<b>CAP Clean</b>	£13,500.00		
<b>Colour</b>	BLACK	<b>CAP Average</b>	£12,750.00		

\*WARNING LIGHT ON DASH\* AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Digital radio
- Cruise control
- Cloth seat trim
- Rear parking sensor
- Auxiliary input socket


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wing nsf  
Dented  
With Paint Damage



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Wing nsf  
Scratched  
Over 25mm Thru Paint



6: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



7: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Qtr Panel nsr  
Dented  
With Paint Damage



11: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



12: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



13: Door nsr  
Scratched  
Over 25mm Thru Paint



14: Door osr  
Dented  
With Paint Damage





15: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



16: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



17: Seat Base Cover osf  
Soiled  
Light



18: Seat Base Cover nsf  
Soiled  
Light



19: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm



20: Dash Warning Lights  
Displayed  
No Action

## Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Average	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		