

VEHICLE INSPECTION REPORT

1/-1-1-1-

KX16FFD

Volvo FH 460

Inspection		Vehicle				
Serious Damage?	No	VAT	Plus VAT			
		V5	Buyer To Apply			
Details						
Reg. date	17/03/2016	VIN	YV2RTY0C0GB765138	Axle Combi	6x2	
Year	2016	Body Style	Tractor Unit	Steering Combi	Mid-Lift	
Mileage	1,040,686 Km Not Warranted	MOT Due	31/01/2026	Rear Suspension	Air	
		Cab Type	GLOBETROTTER CAB			
Fuel Type	Diesel	 Gearbox	AUTOMATIC			
Colour	MULTI-COLOURED					

WARNING LIGHT ON DASH

Tyres

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	_
Spare	NSO1	NSO2	NSO3	NSO4	_
	OS01	OSO2	OS03	OSO4	_

Features

- Bluetooth connection
- Air conditioning
- · Cruise control
- Front electric windows
- Park assist camera
 Control looking
- Central locking
- Digital radio
- Partial leather seat trim

Photos




















Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Bumper Front Chipped Multiple Chips



3: Door Moulding nsf Missing Replace



4: Bonnet Dented With Paint Damage



5: Door nsf Dented With Paint Damage



6: Door nsf Scratched Over 25mm Thru Paint



7: Qtr Panel Moulding os Scuffed (Unpainted) Over 100mm



8: Qtr Panel Trim os Broken Replace



9: Door Moulding osf Missing Replace



10: Screen Front Chipped Over 10mm



11: Door Window nsf Scratched Over 30mm



12: Door Pad osf Soiled Heavy



13: Dash Warning Lights Displayed No Action

Interior

Carpet Condition	OK	•	holstery Condition	Poor	
Seat Condition	OK	Oc	dour	-	
Engine Runs		OK 1	No Excessive Smoking		OK
EML light illuminated		OK [OPF light illuminated		OK
ABS light illuminated		Fault			