

VEHICLE INSPECTION REPORT

DK17LJL

Man TGM 18.250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	24/06/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMAN08ZZ5HY360080	Gearbox	MANUAL
Mileage	201,639 Km Warranted	Body Style	Dropside & Crane	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	28/02/2026	Rear Suspension	Steel

HMF 1420K-RC REMOTE CRANE (YEAR 2017), SURROUND CAMERA SYSTEM, SERVICE SCHEDULE LIST AVAILABLE

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: A Post os
Cracked
Replace



3: Bonnet
Cracked
Replace



4: Bonnet
Cracked
Replace



5: Fog Lamp Surround ns
Scuffed (Unpainted)
Over 100mm



6: A Post ns
Scratched
Over 25mm Not Thru Paint



7: Door Mirror Assy nsf
Missing
Replace



8: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Bumper Rear
Rusted
Over 5mm



13: Lamp nsr
Broken
Replace



14: Other
N/A
N/A



15: Door osf
Dented
Over 2 UpTo 10mm



16: Door osf
Chipped
Edge Chip



17: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



18: Carpets Front
Holed
Over 3mm



19: Seat Base Cover osf
Holed
Over 3mm



20: Centre Console Front
Broken
Replace




21: Door Pad osf
Broken
Replace



22: Handle Inner osf
Damaged
Replace



23: Other
N/A
N/A



24: Other
N/A
N/A

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK