

# VEHICLE INSPECTION REPORT

**YA17SVC**

## Daf LF 150

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date	24/07/2017	VIN	XLRAEL1500L465241	Axle Combi	4x2
Year	2017	Body Style	Box Van	Rear Suspension	Steel
Mileage	280,269 Km Warranted	MOT Due	31/05/2026	Rear Doors	Roller
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Column
Colour	SILVER	Gearbox	MANUAL		

H/CURTAIN, SERVICE SCHEDULE LIST AVAILABLE

### Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Park assist camera


## Photos







## Condition Check



## Damage Photos



1: Bumper Front Moulding  
Scratched (Painted)  
Over 25mm Thru Paint



2: Wing osf  
Chipped  
Multiple Chips



3: Bonnet  
Chipped  
Multiple Chips



4: Bumper Front Moulding  
Scratched (Painted)  
Over 25mm Thru Paint



5: Wing nsf  
Scratched  
Over 25mm Thru Paint



6: Other  
N/A  
N/A



7: Other  
N/A  
N/A



8: C Post ns  
Dented  
Between 10mm + 30mm





9: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



10: Qtr Panel osr  
Dented  
Between 10mm + 30mm



11: Other  
N/A  
N/A



12: Other  
N/A  
N/A



13: Seat Base Cover osf  
Holed  
Over 3mm

## Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	