

# VEHICLE INSPECTION REPORT

**SN70YBV**

## Daf LF 290

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 03/11/2020

Year 2020

Mileage 97,234 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRAEL3700L497141

Body Style Dropside & Crane

MOT Due 30/11/2025

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Steel

\*WARNING LIGHTS ON DASH\* HIAB X-HIDUO 118 REMOTE CRANE (YEAR 2020), SURROUND CAMERA SYSTEM

### Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3

OSO4


## Features

- Park assist camera
- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Wing osf  
Scratched  
UpTo 25mm Thru Paint



2: Bumper Front  
Chipped  
Multiple Chips





3: Bumper Front  
Chipped  
Multiple Chips



4: Other  
N/A  
N/A




5: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm



6: Other  
N/A  
N/A



7: Other  
N/A  
N/A



8: Door osf  
Scratched  
Over 25mm Thru Paint



9: Door osf  
Chipped  
Edge Chip



10: Other  
N/A  
N/A



11: Seat Base Cover osf  
Holed  
Over 3mm

**Interior**

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Average	Average	Average	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK