

## VEHICLE INSPECTION REPORT

**SL12FKE**

### Volkswagen Crafter CR35 Tdi 109ps LWB

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Present

#### Details

Reg. date 30/03/2012

Year 2012

Mileage 125,533 Miles Not Warranted

Fuel Type Diesel

Colour White

VIN WV1ZZZ2FZC7008068

Body Style Tipper Double Cab

Keys 2

Gearbox MANUAL

#### Tyres

NSF

NSR

OSF

OSR


Spare

### Features

- Front electric windows


### Photos







## Condition Check



## Damage Photos



1: Sill os  
Rusted  
Over 5mm



2: Bonnet  
Dented  
Over 30mm



3: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



4: Door osf  
Dented  
With Paint Damage



5: B Post os  
Rusted  
Over 5mm



6: Door osr  
Rusted  
Over 5mm



7: Qtr Panel osr  
Dented  
With Paint Damage



8: Tailgate  
Dented  
With Paint Damage





9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Door nsr  
Dented  
With Paint Damage



11: B Post ns  
Rusted  
Over 5mm



12: Door Moulding nsf  
Broken  
Replace



13: Wing nsf  
Dented  
With Paint Damage

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No