

VEHICLE INSPECTION REPORT

MV68XWD

Ford Transit 350 2.0 TDCI 130PS

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	06/11/2018	VIN	WF0XXXTTGXJM54524	CAP Below	£2,800.00
Year	2018	Body Style	Panel Van L3	Gearbox	MANUAL
Mileage	125,240 Miles Warranted	MOT Due	13/11/2025	Gears	6
		CAP Clean	£4,175.00		
Fuel Type	Diesel	CAP Average	£3,600.00		
Colour	WHITE				

SIDE LOADING DOOR, AD BLUE

CIDE LONDING DO	011,710 0202			
Tyres				
Tyres NSF				
NSR OSF				
OSF				
OSR				
Spare				

Features

Front electric windows

Photos
















Condition Check



Damage Photos



1: Bumper Front Moulding Scuffed (Unpainted) Over 100mm



2: Other N/A N/A



3: Bonnet Chipped Multiple Chips



4: Bumper Front Dented Over 30mm



5: Wing nsf Scratched UpTo 25mm Thru Paint



6: Moulding nsf Wing Scuffed (Unpainted) Over 100mm



7: Door Mirror Assy nsf Broken Replace




8: Flasher Side Repeater ns Broken Replace



9: Door Mirror Glass ns Broken Replace



10: Door nsf Scratched Over 25mm Thru Paint



11: Door nsf Dented Between 10mm + 30mm



12: Other N/A N/A



13: Qtr Panel Trim ns Scuffed Over 25mm



14: Door nsr Chipped Multiple Chips



15: Qtr Panel nsr Dented Between 10mm + 30mm



16: Qtr Panel nsr Dented With Paint Damage



17: Qtr Panel Moulding ns Scuffed (Unpainted) Over 100mm



18: Bumper Rear Moulding Broken Replace



19: Lamp nsr Broken Replace



20: Door nsr Dented With Paint Damage



21: Bumper Rear Moulding Broken Replace



22: Qtr Panel Trim os Scuffed Over 25mm



23: Qtr Panel Arch Extension os Scuffed (Unpainted) UpTo 100mm



24: Qtr Panel osr Dented Between 10mm + 30mm



25: Qtr Panel Moulding os Scuffed (Unpainted) Over 100mm



26: Qtr Panel Moulding os Scuffed (Unpainted) Over 100mm



27: Door Mirror Glass os Missing Replace



28: Door Mirror Assy osf Broken Replace



29: Other N/A N/A



30: Other N/A N/A



31: Seat Base Cover nsf Burn Over 3mm

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average No	
Engine Runs		OK	Gearbox 1st and Revers	se Test	OK
Brakes		OK	Clutch Slip Test from St	atic	OK
Parking Brake		OK	Gearbox Static Gear Se	lection (engine running)	OK
			No Excessive Smoking		OK
EML light illuminated		ОК	Oil warning light illumina	ated	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light ille	uminated	OK