

## VEHICLE INSPECTION REPORT

**LA21UUX**

### Citroen Relay 35 2.2 Bluehdi Enterprise

**Non Runner**  
Inspection

<b>Serious Damage?</b>	No	<b>Vehicle</b>	
		<b>VAT</b>	Plus VAT
		<b>V5</b>	Buyer To Apply

#### Details

<b>Reg. date</b>	31/05/2021	<b>Colour</b>	Grey	<b>CAP Average</b>	£7,675.00
<b>Year</b>	2021	<b>VIN</b>	VF7YCBNFC12S85262	<b>CAP Below</b>	£6,450.00
<b>Mileage</b>	71,987 Miles Not Warranted	<b>Body Style</b>	Panel Van L3	<b>Gearbox</b>	MANUAL
<b>Fuel Type</b>	Diesel	<b>CAP Clean</b>	£8,450.00		

\*GEARBOX ISSUE - NO 1ST OR 2ND GEAR\*\*WARNING LIGHT ON DASH\*  
AD-BLUE, SIDE LOAD DOOR, E/ MIRRORS

#### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Cruise control
- Front electric windows
- Navigation system
- Drivers airbag
- Rear parking sensor
- Central locking


## Photos







## Condition Check



## Damage Photos



1: Wing nsf  
Dented  
With Paint Damage



2: Door nsf  
Chipped  
Multiple Chips



3: Door Mirror Glass ns  
Missing  
Replace



4: Door nsf  
Chipped  
Edge Chip




5: Door nsf  
Scratched  
Over 25mm Not Thru Paint



6: Panel Front  
Scratched  
Over 25mm Not Thru Paint



7: Panel Front  
Scratched  
Over 25mm Not Thru Paint



8: Panel Rear  
Scratched  
UpTo 25mm Not Thru Paint





9: Panel Rear  
Dented  
With Paint Damage



10: Panel Rear  
Scratched  
Over 25mm Not Thru Paint



11: Panel Rear  
Scratched  
Over 25mm Not Thru Paint



12: Panel Front  
Scratched  
Over 25mm Not Thru Paint



13: Bumper Front  
Insecure  
Action Required



14: Panel Rear  
Dented  
Between 10mm + 30mm



15: Panel Rear  
Dented  
Over 30mm



16: Panel Rear  
Dented  
Over 30mm



17: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



18: Panel Rear  
Scratched  
Over 25mm Not Thru Paint



19: Panel Rear  
Dented  
Over 30mm



20: Qtr Panel Trim os  
Missing  
Replace





21: Panel Rear  
Dented  
Over 30mm



22: Panel Front  
Scratched  
Over 25mm Not Thru Paint



23: Panel Front  
Scratched  
Over 25mm Not Thru Paint



24: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm



25: Carpets Front  
Holed  
Over 3mm



26: Seat Base Cover osf  
Soiled  
Light



27: Seat Base Cover nsf  
Soiled  
Light

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No