

VEHICLE INSPECTION REPORT

FN17BOH

Daf LF 180

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Present

Details

Reg. date	23/05/2017	Colour	WHITE	Gearbox	AUTOMATIC
Year	2017	VIN	XLRAEL1500L462436	Axle Combi	4x2
Mileage	326,371 Km Not Showing	Body Style	Curtainside	Tail Lift	Cantilever
Fuel Type	Diesel	Cab Type	DAY CAB		

NON RUNNER- ENGINE FAULTY, DOES NOT POWER UP

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Sill Panel Trim ns
Broken
Replace



2: Door osf
Chipped
Multiple Chips



3: Seat Back Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Poor	Odour		-
Engine Runs		Fault	Gearbox 1st and Reverse Test		Fault
Brakes		Fault	Clutch Slip Test from Static		Fault
Turbo Boosting		Fault	Gearbox Static Gear Selection (engine running)		Fault
Parking Brake		Fault	No Excessive Smoking		Fault
EML light illuminated		Fault	Oil warning light illuminated		Fault
Airbag light illuminated		Fault	Service indicator light illuminated		Fault
ABS light illuminated		Fault			