

# VEHICLE INSPECTION REPORT

**C291659**

## Iveco Stralis 460

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date

Colour

WHITE

Gearbox

AUTOMATIC

Year

VIN WJMM1VTH60C291659

Axle Combi

4x2

Mileage

186,145 Km Not Warranted

Body Style

Tractor Unit

Rear Suspension

Air

Fuel Type

DIESEL

Cab Type

HI-WAY CAB

SLIDING 5TH WHEEL

### Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4


## Features

- Bluetooth connection
- Radio/CD
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Digital radio
- Central locking

## Photos












## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips






3: Bumper Front Moulding  
Missing  
Replace



4: Bumper Front  
Scratched  
Over 100mm Thru Paint



5: Door nsf  
Scratched  
Over 25mm Thru Paint



6: Door Mirror Assy nsf  
Missing  
Replace



7: Wing nsf  
Scratched  
Over 25mm Thru Paint



8: Qtr Panel Moulding ns  
Broken  
Replace



9: Qtr Panel nsr  
Chipped  
Multiple Chips



10: Qtr Panel Trim ns  
Broken  
Replace



11: Qtr Panel Trim os  
Broken  
Replace



12: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm



13: Screen Front  
Chipped  
Over 10mm



14: Door Pad osf  
Broken  
Replace



15: Fascia Panel  
Scuffed  
Over 25mm

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		