

VEHICLE INSPECTION REPORT

YB64AEK

Renault Kangoo ML19dCi 90 eco2

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 14/01/2015

Year 2015

Mileage 63,822 Miles Not Warranted

Fuel Type Diesel

Colour White

VIN VF1FW18B552008375

Body Style Panel Van SWB

MOT Due 15/06/2025

CAP Clean £1,975.00

CAP Average £1,625.00

CAP Below £1,175.00

Gearbox MANUAL

SIDE LOAD DOOR, ROOF RACK

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Qtr Panel nsr
Chipped
Multiple Chips



3: B Post ns
Chipped
Multiple Chips



4: D Post os
Chipped
Multiple Chips



5: Qtr Panel osr
Dented
Over 30mm



6: Qtr Panel osr
Chipped
Multiple Chips



7: B Post os
Chipped
Multiple Chips



8: Door Pad osf
Scuffed
Over 25mm



9: Fascia Panel
Soiled
Heavy



10: Seat Base Cover osf
Holed
Over 3mm



11: Seat Base Cover nsf
Soiled
Heavy



12: Wing osf
Cracked
Replace



13: Wing nsf
Cracked
Replace

Interior

Carpet Condition
Seat Condition

OK
Poor

Upholstery Condition
Odour

Poor
No