

VEHICLE INSPECTION REPORT

SJ15TWK

Vauxhall Vivaro 2900 1.6CDTI 115PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 25/03/2015

Year 2015

Mileage 77,989 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN W0L3F7018FV625633

Body Style Panel Van LWB

Keys 1

MOT Due 06/02/2026

CAP Clean £3,125.00

CAP Average £2,575.00

CAP Below £1,875.00

Gearbox MANUAL

Gears 6

Doors 2

Steering Combi Standard Axle

Rear Suspension Steel

SINGLE SIDE DOOR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Carpets Front
Torn
Over 10mm



2: Seat Base Cover osf
Torn
Over 3mm



3: Sill os
Dented
Over 30mm



4: Bonnet
Dented
With Paint Damage



5: Wing osf
Rusted
Over 5mm



6: Door osf
Dented
Over 2 UpTo 10mm



7: Qtr Panel osr
Dented
With Paint Damage



8: Tailgate
Dented
With Paint Damage



9: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



10: Qtr Panel nsr
Dented
With Paint Damage



11: Door nsr
Dented
Over 30mm



12: Door nsf
Dented
With Paint Damage



13: Wing nsf
Rusted
Over 5mm



14: Door Mirror Assy nsf
Broken
Replace

Interior

Carpet Condition		Poor Poor	Upholstery Condition		Average No
Seat Condition			Odour		
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	
Windows	OK		Radio	OK	
			Steering	OK	